						,
S11	9434	S6 and (belt loop rope)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/25 12:51
S12	9175	S11 and (drive\$2 power)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/25 12:52
S13	2570	S12 and (endless continuous) and (loop)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/25 12:52
S14	1	"4909086".pn.	USPAT	OR	OFF	2005/08/26 08:39
S15	1	("4909086").URPN.	USPAT	OR	OFF	2005/08/26 08:39
S16	6	circumferential\$5 near4 (bearing near3 (measure\$5 test\$4 identi\$6 evaluate\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	USPAT	OR	OFF	2005/08/26 15:02
S17	8	circumferential\$5 near4 (bearing near3 (measure\$5 test\$4 identi\$6 evaluate\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/26 15:14
S18	3	("4035043").URPN.	USPAT	OR	OFF	2005/08/26 15:00
S19	8	circumferential\$5 near4 (bearing near3 (measure\$5 test\$4 identi\$6 evaluate\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/08/26 15:02
S20	. 24	circumferential\$5 near4 (bearing near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/26 15:38
S21	2	"5140849".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/26 15:38

S22	25	("3088083" "3137834" "4145930" "4203319" "4341122" "4793189" "5038616").PN. OR ("5140849").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/26 15:43
S23	20	("4203319").URPN.	USPAT	OR	OFF	2005/08/26 15:57
S24	1	"5140849".pn.	USPAT	OR	OFF	2005/08/29 07:03
S25	1	"4748844".pn.	USPAT	OR	OFF	2005/08/29 07:03